## **SN38 Returned to Service**

Submitted by MattWingo on Fri, 2013-05-17 21:11 Date: Friday, May 17, 2013 - 21:00

## **Instrument List:**

• Green

## Discussion:

Camera 'a' was replaced in SN38 today. The unit was calibrated and is now back to collecting data. 2, 4, and 6 mm sphere diameters and oblateness looked good after calibration.

All six of the 2DVDs are now collecting data.